Certificate of Registration

This certifies that the Quality Management System of

Turbine Controls, LLC

#5 Old Windsor Road
Bloomfield, Connecticut, 06002, United States

has been assessed by NSF-ISR and found to be in conformance to the following standard(s):

AS9100D with ISO 9001:2015

*Audited in accordance with AS9104/1:2012 Requirements for Aviation, Space, and Defense Quality Management System Certification Programs. NSF-ISR is accredited under the Americas Aerospace Quality Group Registration Management Committee.

Scope of Certification:

Several Sites: The Overhaul and Repair of Rotating and Stationary Component Supports, including Disk, Shafts, Hubs, Seal Housing and Support of Fuel, Oil Pneumatic Engine/Airframe Accessories.

Certificate Number:	64531-AS15
Certificate Decision/Re-Issue Date:	19-JUN-2025
Certificate Issue Date:	15-SEP-2025
Certificate Expiration Date*:	14-SEP-2028

Sameer Vachani
Senior Director, NSF-ISR

Issued by:
NSF International Strategic Registrations (NSF-ISR)
789 N. Dixboro Road, Ann Arbor, MI 48105 USA

Authorized Certification and/or Accreditation Marks. This certificate is property of NSF-ISR and must be returned upon request.

Company is audited for conformance at regular intervals. To verify certification call (888) NSF-9000 or visit our web site at www.nsf-isr.org

ANAB
ANSI National Accreditation Board
ACCREDITED
ISO/IEC 17021-1
MANAGEMENT SYSTEMS CERTIFICATION BODY

Certificate of Registration

ANNEX PAGE FOR CERTIFICATE NUMBER: 64531-AS15

CERTIFICATE DECISION/ RE-ISSUE DATE:
19-JUN-2025
CERTIFICATE ISSUE DATE:
15-SEP-2025
CERTIFICATE EXPIRATION DATE:
14-SEP-2028

Turbine Controls, LLC
#5 Old Windsor Road
Bloomfield, Connecticut, 06002, United States

Location:	Scope:
Turbine Controls, LLC 3501 Enterprise Way Miramar, Florida, 33025, United States	**The Overhaul and Repair of fuel, oil pneumatic engine/ airframe accessories.**
Location:	**Scope:**
Turbine Controls, LLC #5 Old Windsor Road Bloomfield, Connecticut, 06002, United States	**(Central Office) The Overhaul and Repair of Rotating and Stationary Component Supports, including Disk, Shafts, Hubs, and Seal Housing as conducted at #5, #2 and #4 Old Windsor Road, Bloomfield, CT 06002.**

This Annex is only Valid in connection with the above-mentioned certificate issued by NSF-ISR

Issued by:
NSF International Strategic Registrations (NSF-ISR)
789 N. Dixboro Road, Ann Arbor, MI 48105 USA

Authorized Certification and/or Accreditation Marks. This certificate is property of NSF-ISR and must be returned upon request.

Company is audited for conformance at regular intervals. To verify certification call (888) NSF-9000 or visit our web site at www.nsf-isr.org

ANAB
ANSI National Accreditation Board
ACCREDITED
ISO/IEC 17021-1
MANAGEMENT SYSTEMS CERTIFICATION BODY